
How to install UART Daughter Board to the VSI-Pro Max.

1.) Take the cover off with 6 screws.








2.) Prepare UART Board and Stand.



3.) Plug stand into the UART Board at the red point follows picture below.







4.) Plug the UART Board install to the VSI-Pro Max.



Put UART Board with stand into the red point on the VSI-Pro Max.





5.) Finished close all cover.